



# Ravnanger secondary school

## Secondary school



Ravnanger Secondary School | Photo: Multiconsult

Multiconsult assisted Askøy Municipality with the refurbishment of Ravnanger secondary school in Hauglandshella.

The project involved replacing windows and doors, painting exterior walls and some concrete repairs. New roof coverings were installed. Fascia boards and cladding on eaves and exterior walls were replaced as required. Walls were upgraded to meet current fire regulations. Sun shades were installed. Floor coverings were replaced in most of the school.

In conjunction with the replacement of the ventilation system, four new roof vents were added, in addition to the existing one. A new rubbish shed was also built, and the structure and buildings services for the outdoor pupil toilets were refurbished. The project was split into a number of separate contracts.

### PROJECT

Ravnanger secondary school

### PROJECT TYPE

Refurbishment – structural, fire safety

### LOCATION

Hauglandshella in Askøy

### CLIENT

Askøy Municipality, Property

### TIME PERIOD

2009 - 2013

### KEY NUMBERS

Year of construction: 1998 | Gross floor space approx. 4,500 m<sup>2</sup>

## SCOPE OF WORK

text

## OUR SERVICES

- Design
- Design management
- Responsible applicant
- Recommending bids
- Contracting
- Site management

## DISCIPLINES

- text



New ventilation houses | Photo: Multiconsult



Top: New roof | Photo: Multiconsult  
Bottom: Ventilation, electro and automation | Photo: Multiconsult

01\_000\_00.00.2016